Material Safety Data Sheet

May be used to comply with OSHA's Hazard Communication Standard,

29 CFR 1910.1200. Standard must be sulted für specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration (Non-Mandatory Form)

Form Approved

OMB No. 1218-0072



IDENTITY (As Used on Label and List) Resin bonded grinding wheels Note: Blank spaces are not permitted. If any item is not applicable, or no information is available, the space must be marked to indicate that Section I Emergency Telephone Number (503) 234-0733 Manufacturer's Name Western Abrasives, Inc. & Beaver State Abr. Address (Number, Street, City, State, and ZIP Code) Telephone Number for Information 2105 S.E. 6th Ave. (503) 234-0733 Date Prepared Portland, OR 97214 November 24, 1987 Supersedes previous MSDS Signature of Preparer (optional) Section II - Hazardous Ingredients/Identity Information Other Limits % (optional) Hazardous Components (Specific Chemical Identity, Common Name(s)) OSHA PEL ACGIH TLV Recommended SEE PAGE 3 ATTACHMENT Section III — Physical/Chemical Characteristics **Boiling Point** Specific Gravity (H₂O = 1) NAIF NAIF Vapor Pressure (mm Hg.) **Melting Point** NAIF NAIF Vapor Density (AIR - 1) Evaporation Rate NAIF NAIF (Butyl Acetate = 1) Solubility in Water NAIF Appearance and Odor A solid which breaks down during use to dust. Dust may have a mild odor. Section IV — Fire and Explosion Hazard Data Flash Point (Method Used) NAIF UEL Flammable Limits NAIF NAIF NAIF Extinguishing Media Water Special Fire Fighting Procedures Approved breathing apparatus may be necessary where dangerous accumulations of toxins occur. (See section V) Unusual Fire and Explosion Hazards Accumulations of dust of some ingredients pose explosion hazards, but

are not expected to be a problem in normal grinding procedures.

Section V -	- Resctivity Do	a t n					
Stability	Unstable		Conditions to Avoid		•		<i>:</i>
	Stable	X					
ncompatibility	(Materials to Avoi	id) Fluor	ino gas saids	CO ovidiza			
nazardous Deco	omposition or Bypro	oducts Com	rine gas, acids, nbustion - CO ₂ ; C	0. fluoride	sodium ovid	o notassium	oxide fumes
Hazardous	May Occur	Con	Conditions to Avoid	o, Truoride,	Soutum Oxid	e, pocassian	OXIGE Tailes
Polymerization	Will Not Occur			·			
	. VVIII 1400 CCCCII	Х					
	- Health Haza						
Route(s) of Entr		nhalation?	yes	Skin? yes		Ingestion?	likely
Health Hazards Nuisance	(Acute and Chronic dust is cre	c) ated du	ring grinding op	erat <u>ions whi</u>	ch may cause	eye, skin an	<u>d respirato</u>
			for more inform				
			noted in sectio	•		•	
Carcinogenicity:		ITP?		IARC Monographs	?	OSHA Regulated	?
					:		
Signs and Symp	otoms of Exposure	Drv mu	cous membranes;	red scratchy	eves, nose,	throat and s	kin.
	· · · · · · · · · · · · · · · · · · ·		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				e selene
Medical Condition	ons	Dno ov	isting wosnimate	ny problems i	nav bo aggra	vated by eyno	sure to
	vated by Exposure	rre-ex	isting respirato	ry problems	ilay be ayyra	vaced by expo	, sure to
dust	First Aid Procedur	es The 21	ation: remove to	froch sin	Evec: flush	with water	Skin: wash
						with water.	JKIII. Wasii
		 	ritation persist	s, consure p	nysteran.		· · · · · · · · · · · · · · · · · · ·
	en in Case Materi		e Handling and Use				
			sed or Spilled NA	· · · · · · · · · · · · · · · · · · ·			544
					 		. Decini
		<u> </u>			· 	·	
Waste Disposal	Method Stan	dard la	ndfill.				. BANKE'S
Precautions to E	Be Taken in Handli	ing and Sto	Do not handle	e roughly.	Inspect for	defects befor	e using.
Store awa	y from heat	and mo					
Other Precaution	<u> </u>		r.p.m. ratings.				
					· ·		
Section VIII	- Control Me	acurae					
			that comply wit	- OCHA 20 CE	D 1010 124		
Ventilation	Local Exhaust	Masks	that comply with	. Specia		····	
yes.	recommende		intain TLV		none		
		d to ma	intain TLV	Other	none		· · · · · · · · · · · · · · · · · · ·
Protective Glove	s optional	· 		Eye Protection Required	- see OSHA 2	9 CFR 1910.13	3
Other Protective Hearing	Clothing or Equiporotection -	ment see OS	HA 29 CFR 1910.2	15. Face shi	eld, apron r	ecommended.	
			while using prod				iting.